



BRAKE REPAIR KITS

RETRO-FITS SPIDERS WITH 1" ANCHOR PIN TO "FC-III" SHOE						
	LB-12	REPLACES				
	2 - B151 Retainer 2 - B216 Anchor Pin 2 - B220 Spring 1 - B307 Spring 2 - B362 Bushing 4 - B380 Lock 4 - B392 Washer 2 - B423 Pin 2 - B911 Roller	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 50%; text-align: center;">LB-12</th> <th style="width: 50%; text-align: center;">LB-12R</th> </tr> </thead> <tbody> <tr> <td style="font-size: x-small;"> Batco BWP Euclid Leland Meritor Midland Spicer </td> <td style="font-size: x-small; text-align: center;"> 08-105010 08-105010 </td> </tr> </tbody> </table>	LB-12	LB-12R	Batco BWP Euclid Leland Meritor Midland Spicer	08-105010 08-105010
	LB-12	LB-12R				
Batco BWP Euclid Leland Meritor Midland Spicer	08-105010 08-105010					
LB-12R	FMS LINING NUMBER(S)					
2 - B434S Spring (Replaces B220)	4661 (5") 4536 (5-1/2") 4692 (7-1/2")					

SPECIAL KIT CONTAINS 1" AND 1-1/4" ANCHOR PINS				
	LB-10S	REPLACES		
	2 - B120 Anchor Pin 2 - B151 Retainer 2 - B216 Anchor Pin 1 - B307 Spring 4 - B380 Lock 4 - B392 Washer 2 - B423 Pin 2 - B434S Spring 2 - B586 Roller 2 - B888 Bushing	<table border="1" style="width: 100%; border-collapse: collapse;"> <tbody> <tr> <td style="font-size: x-small;"> Batco BWP Euclid Leland Meritor Midland Spicer </td> <td style="font-size: x-small; text-align: center;"> HK49-150 </td> </tr> </tbody> </table>	Batco BWP Euclid Leland Meritor Midland Spicer	HK49-150
	Batco BWP Euclid Leland Meritor Midland Spicer	HK49-150		
FMS LINING NUMBER(S)	4661 (5") 4536 (5-1/2") 4692 (7-1/2")			

