







# CAMSHAFT SUPPORT BRACKETS

PART NO.	NOTES	REPLACES	
 <b>B8734</b>	For Fruehauf	Batco BWP Euclid Fruehauf Leland Meritor Spicer	03-251 M-1048  AXA0430-1 L-899  30-1363
 <b>B8728</b>	For Fruehauf 16-1/2" Axle Bracket	Batco BWP Euclid Fruehauf Leland Meritor Spicer	03-273 M-2595 E-4586 ACF4024-1 L-2712 R630006 30-1392
 <b>B8727</b>	For Fruehauf 12-1/4" And 16-1/2" Brakes	Batco BWP Euclid Fruehauf  Leland Meritor Spicer	03-272  E-4587 ACF4021-1 ACF4022-1 L-2711 R630007
 <b>B8727A</b>	For Fruehauf 12-1/4" And 16-1/2" Brakes  B8727 Assembly And B8624 Bushing	Batco BWP Euclid Leland Meritor Spicer	03-279 M-2594   30-1390
 <b>B8725</b>	For Fruehauf 16-1/2" Brakes  Includes B8728 Bracket And B8727 Assembly	Batco BWP Euclid Leland Meritor Spicer	03-270  L-2707
 <b>B8725A</b>	Same As Above Except Includes B8624 Bushing	Batco BWP Euclid Fruehauf Leland Meritor Spicer	03-278  E-4594 ACF4024-900 L-3040 R630009