






CAMSHAFT SEALS

	PART NO.	O.D.	I.D.	THK	REPLACES
	B8613	1-3/4"	1-31/64"	1/8"	Batco 02-306 BWP M-825 Euclid E-1272 Leland L-1768 Meritor 1205N924 Spicer 29-1267
	Inboard Seal In B8660 Assembly				
	B8626	1-7/8"	1-5/8"	1/8"	Batco 02-309 BWP M-1403 Euclid E-2406 Leland L-1295 Meritor 1205V1452 Spicer 29-1275
	Inboard Seal In B8661 Assembly				
	B8621				
	Used In B8696 On 1-1/2" Diameter Camshafts	1-29/32"	1-1/2"	13/32"	Batco 03-213 BWP M-1093 Euclid E-1314 Leland L-1729 Meritor 1205X726 Spicer 27-1208
	B8690	2-1/16"	1-7/8"	1/8"	Batco 02-329 BWP E-3859 Euclid L-3056 Leland 1205G761 Meritor 30-1375 Spicer
	Gasket For Meritor Drive Axles				
	B8761	1-3/4"	1-3/16"	1/4"	Batco 02-318 BWP M-3236 Euclid E-3878 Leland L-2938 Meritor A1205D2110 Spicer
	For Meritor 15" x 4" "Q" Front Brakes				
	B8751	1-7/8"	1-1/4"	1/16"	Batco 02-315 BWP M-3352 Eaton 1005846 Euclid E-5128 Leland L-2830 Meritor R627030 Spicer
	For Eaton 15" x 4" Front Brakes				

Copyright 2005 Sirco Industries, Inc.