


CAMSHAFT SEALS

	PART NO.	O.D.	I.D.	THK	REPLACES
	B8612	1-7/8"	1-1/2"	3/16"	Batco 02-312 BWP M-824 Euclid E-1416 Leland L-1770 Meritor 1205M1105 Spicer 29-1269 M16HH100
	For Meritor And Spicer 1-1/2" Diameter Camshafts				
	B8612A	1-7/8"	1-1/2"	1/4"	Batco 02-304 BWP M-824A Eaton 79903 Euclid E-1416A Leland L-966 Meritor R627008 Spicer 29-1266
	For Eaton 1-1/2" Diameter Camshafts				
	B717	2"	1-1/2"	3/16"	Batco 02-317 BWP M-2632 Euclid E-2717 Leland L-1687 Meritor Spicer
	For Hendrickson "Intraax"				
	B8764	2"	1-5/8"	3/16"	Batco BWP M-1401A Euclid E-3991 Leland Meritor Spicer
Use With B8698 In Meritor 4000-6000 Trailer Axles					
B8625	2"	1-5/8"	1/4"	Batco 02-313 BWP M-1401 Eaton 1002279 Euclid E-2405 Leland L-2941 Meritor 1205Q2123 Spicer 29-1274	
For Eaton "501" Brake And In B8661 Assy					
B8755	2-1/16"	1-7/32"	1/4"	Batco 02-316 BWP M-2630 Euclid E-3469 Leland L-1744 Meritor A1205P1602 Spicer 29-1283	
For Meritor 1-1/4" Diameter Front Camshafts					

Copyright 2005 Sirco Industries, Inc.