


# CAMSHAFT WASHERS

	PART NO.	O.D.	I.D.	THK	REPLACES
	<b>B8619</b>	2-3/8"	1-41/64"	.060"	Batco 04-304 BWP M-1045 Euclid E-1565 Fruehauf AXA0417-1 Leland L-895 Meritor R627002 Spicer 29-1322
	For Fruehauf Propar Axles				
	<b>B8611</b>	2-7/16"	1-9/16"	.120"	Batco 04-303 BWP M-719 Euclid E-719 Leland L-344 Meritor 1229M559 Spicer 29-1311 M10HS117 Std Forge 403105
	For Spicer, Standard Forge And Meritor Brakes				
	<b>B8758</b>	2-7/16"	1-9/32"	.032"	Batco 04-345 BWP M-2639 Euclid E-3475 Leland L-1748 Meritor 1107D56 Spicer 29-1334
	For Meritor 15" x 4" "T" Brakes				
	<b>B800</b>	2-7/16"	1-11/16"	.120"	Batco 04-329 BWP M-3985 Euclid E-10800 Leland L-3178 Meritor R627043 Spicer M10HS143
Dana With 1-5/8" Cam Journal					
<b>B8756</b>	2-1/2"	1-5/16"	.062"	Batco 04-340 BWP M-2640 Euclid E-3471 Leland L-1743 Meritor 1229B236 Spicer 29-1338	
For Meritor 15" x 4" "T" Brakes					
<b>B230</b>	2-3/4"	1-1/2"	.134"	Batco 04-341 BWP M-2641 Euclid E-3472 Leland L-1753 Meritor 1229P302 Spicer 29-1333	
For Meritor 16-1/2" "T" Brakes					

Copyright 2005 Sirco Industries, Inc.