




CAMSHAFT LOCKS

	PART NO.	O.D.	I.D.	THK	REPLACES
	B8622	---	1-1/2"	1/16"	Batco 04-315 BWP M-1046 Euclid E-1569 Fruehauf AXA0418-1 Leland L-897 Meritor R627017 Spicer 29-1302
	For Meritor 4000-6000 And "Propar" Axles				
	B8634	---	1-1/2"	1/16"	Batco 04-314 BWP M-1505 Euclid E-910 Leland L-467 Meritor R627014 Spicer 29-1315
	For 1-1/2" Diameter Camshafts				
	B8634A	---	1-5/8"	3/32"	Batco 04-363 BWP M-3398 Euclid E-9077 Leland L-3364 Meritor 1229T4102 Spicer 29-1305
	For Meritor 16-1/2" "Q-Plus" Brakes				
	B8722	---	---	---	Batco 04-319 BWP M-2649 Eaton 804017 Euclid E-3234 Leland L-1606 Meritor R627012 Spicer 29-1303
	For Eaton Camshafts				