




BRAKE REPAIR KITS

BENDIX 15" FRONT AXLE BRAKE								
	FF-1	REPLACES						
	2 - B136 Roller Pin 2 - B137 Roller 1 - B138 Anchor Pin 1 - B139 Spring 2 - B140 Spring	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="width: 30%; text-align: center;">FF-1</th> <th style="width: 40%; text-align: center;">FF-1A</th> </tr> </thead> <tbody> <tr> <td style="vertical-align: top;"> Batco Bendix BWP Euclid Leland Meritor Midland Spicer </td> <td style="vertical-align: top; text-align: center;"> 08-114000 104627 M-K94 E-7231 K-297 R507080 CQ65519 HK70 </td> <td style="vertical-align: top; text-align: center;"> 08-114002 K-298 </td> </tr> </tbody> </table>		FF-1	FF-1A	Batco Bendix BWP Euclid Leland Meritor Midland Spicer	08-114000 104627 M-K94 E-7231 K-297 R507080 CQ65519 HK70	08-114002 K-298
		FF-1	FF-1A					
Batco Bendix BWP Euclid Leland Meritor Midland Spicer	08-114000 104627 M-K94 E-7231 K-297 R507080 CQ65519 HK70	08-114002 K-298						
Above Less: 1 - B138 Anchor Pin	FMS LINING NUMBER(S) 4693 (4")							

BENDIX 15" FRONT AXLE BRAKE - SPRINGS ONLY				
	FF-1S	REPLACES		
	2 - B139 Spring 4 - B140 Spring	<table border="1" style="width: 100%; border-collapse: collapse;"> <tbody> <tr> <td style="vertical-align: top;"> Batco Bendix BWP Euclid Leland Meritor Midland Spicer </td> <td style="vertical-align: top; text-align: center;"> 104623 E-7232 </td> </tr> </tbody> </table>	Batco Bendix BWP Euclid Leland Meritor Midland Spicer	104623 E-7232
	Batco Bendix BWP Euclid Leland Meritor Midland Spicer	104623 E-7232		
	FMS LINING NUMBER(S) 4693 (4")			

DANA 15" "HA" SERIES STEER AND LIFT AXLE				
	SF-1	REPLACES		
	1 - B142 Spring 2 - B151 Retainer 2 - B220 Spring 2 - B423 Pin 2 - B586 Roller	<table border="1" style="width: 100%; border-collapse: collapse;"> <tbody> <tr> <td style="vertical-align: top;"> Batco BWP Euclid Leland Meritor Midland Spicer </td> <td style="vertical-align: top; text-align: center;"> 08-116600 E-11493 K-374 HK95XLS </td> </tr> </tbody> </table>	Batco BWP Euclid Leland Meritor Midland Spicer	08-116600 E-11493 K-374 HK95XLS
	Batco BWP Euclid Leland Meritor Midland Spicer	08-116600 E-11493 K-374 HK95XLS		
	FMS LINING NUMBER(S) 4693 (4")			