




RIM CLAMPS

TYPE	PART NO.	STUD	A	B	C	REPLACES
Dayton 	399	5/8"	1/2"	2"	2"	Batco 13-5007 BWP M-27 Dayton 09-839910 Euclid E-5927 GLP GL-3083 Leland W-124 Meritor R005927G Spicer 52-1440
	853	3/4"	1/2"	2"	2"	Batco 13-5012 BWP M-1122 Dayton 09-885310 Euclid E-5926 GLP GL-3085 Leland W-408 Meritor R005926G Spicer 52-1441
	Available In Pails (100)					
Dayton 	729	3/4"	3/16"	2-1/2"	2-5/8"	Batco 13-5020 BWP M-30B Dayton 09-007295 Euclid E-5838 GLP GL-3087 Leland W-407 Meritor R005838G Spicer 52-1436
	123	3/4"	1-1/8"	2-7/8"	2-1/2"	Batco 13-4002 BWP M-3 Dayton 09-612317 Euclid E-5571A GLP GL-3096 Leland W-3 Meritor R005571AG Spicer 52-1301 Webb 16123
	Available In Pails (100)					
Dayton 	708	3/4"	1-3/8"	2-7/8"	2-1/2"	Batco 13-4010 BWP M-1123 Dayton 09-870817 Erie E12 Euclid E-5784A GLP GL-3103 Leland W-405 Meritor R005784AG Spicer 52-1309
	993	3/4"	1-1/2"	2-7/8"	2-1/2"	Batco 13-4004 BWP M-8 Dayton 09-699317 Erie E3 Euclid E-5040A GLP GL-3098 Leland W-120 Meritor R005040AG Spicer 52-1304
	Available In Pails (75)					

Copyright 2005 Sirco Industries, Inc.