







# RIM CLAMPS

TYPE	PART NO.	STUD	A	B	C	REPLACES
Dayton 	<b>235</b>	3/4"	1-3/4"	2-7/8"	2-1/2"	Batco 13-4006 BWP M-4 Dayton 09-623517 Euclid E-5572A GLP GL-3097 Leland W-4 Meritor R005572AG Spicer 52-1306
	Available In Pails (75)					
	<b>053</b>	3/4"	1-7/8"	2-7/8"	2-13/32"	Batco 13-4011 BWP M-1124 Dayton 09-705317 Euclid E-5785A GLP GL-3099 Leland W-406 Meritor R005785G Spicer 52-1310
Dayton 	<b>256</b>	3/4"	1-1/8"	6"	2-7/16"	Batco 13-4723 BWP M-1141 Dayton 09-006256 Euclid E-5827 GLP GL-3112 Leland W-536 Mack 15QJ16 Meritor R005827G Spicer 52-1392
	<b>302</b>	3/4"	1-7/16"	6-5/8"	2-7/16"	Batco 13-4725 BWP M-1105 Dayton 09-006302 Euclid E-5829 GLP GL-3114 Leland W-184 Meritor R005829 Spicer 52-1395
	<b>257</b>	3/4"	1-13/16"	6"	2-7/16"	Batco 13-4724 BWP M-1142 Dayton 09-006257 Euclid E-5828 GLP GL-3113 Leland W-450 Meritor R005828G Spicer 52-1394
Clear Zinc Goodyear 	<b>008</b>	3/4"	1-5/16"	2-1/2"	2-13/16"	Batco 13-4850 BWP M-1282 Euclid E-5885 GLP GL-3158 Goodyear CL1008 Leland W-456 Meritor R005885G Spicer 52-1385
Yellow Zinc						

Copyright 2005 Sirco Industries, Inc.