







# RIM CLAMPS

TYPE	PART NO.	STUD	A	B	C	REPLACES
Gunite 	<b>138</b>	3/4"	1-3/8"	2-7/8"	2-3/8"	Batco 13-4531 BWP M-1242 Euclid E-5904A GLP GL-3255 Gunite W1138 Leland W-257 Meritor R005904A Spicer 52-1337
Gunite 	<b>267</b>	3/4"	1-1/16"	2-3/8"	1-3/4"	Batco 13-4601 BWP M-1134 Euclid E-5747 GLP GL-3257 Gunite WP267 Leland W-135 Meritor R005747 Spicer 52-1370
Mack 	<b>251</b>	3/4"	5/16"	2-1/2"	2-5/8"	Batco 13-5016 BWP M-3213 Euclid E-6053 GLP GL-3263 Leland W-565 Mack 15QJ251 Meritor R006053G Spicer 52-1403
Mack 	<b>238</b>	3/4"	1-7/8"	2-1/2"	2-7/16"	Batco 13-4702 BWP M-1175 Euclid E-5781 GLP GL-3271 Leland W-448 Mack 15QJ223BP8 Meritor R005781G Spicer 52-1380
Mack 	<b>233</b>	3/4"	2-1/8"	2-1/2"	2-7/16"	Batco 13-4704 BWP M-1249 Euclid E-5821 GLP GL-3279 Leland W-467 Mack 15QJ223BP3 Meritor R005821G Spicer 52-1382
Mack 	<b>236</b>	3/4"	2-3/8"	2-1/2"	2-7/16"	Batco 13-4703 BWP M-1127 Euclid E-5783 GLP GL-3270 Leland W-449 Mack 15QJ223BP6 Meritor R005783 Spicer 52-1381
Rear						

Copyright 2005 Sirco Industries, Inc.