




# BRAKE REPAIR KITS

EATON 15" "EB" AND "ES" SERIES			
	EF-1		REPLACES
	1 - B562	Spring	Batco 08-111300
	2 - B725	Roller	BWP M-K77
1 - B999	Spring	Eaton 1008306	
			Euclid E-5139
			E-1308E
			Leland K-263
			Meritor R507004
			MKT1308E
			Midland C66917
			CQ66917
			Spicer HK54
			FMS LINING NUMBER(S)
			1308 (4")
			1443TT (4")

EATON 15" x 6" "ES" AND "ES-II" REDUCED ENVELOPE FRONT BRAKE			
	ES-3		REPLACES
	2 - B220	Spring	ES-3
	2 - B430K	Roller	ES-3R
2 - B431	Retainer	Batco 08-104300	
2 - B433	Spring	BWP M-K114	
		Eaton 823141	
		Euclid E-9141	
		Leland K-356	
		Meritor R507086	
		Midland CQ66947	
		Spicer HK90XLS	
			FMS LINING NUMBER(S)
			4716 (6")

EATON 15" "ES-II" FRONT BRAKE			
	ES-5		REPLACES
	2 - B430K	Roller	Batco 08-114700
	2 - B431	Retainer	BWP
2 - B434	Spring	Eaton	
1 - B871	Spring	Euclid	
		Leland	
		Meritor	
		Midland	
		Spicer	
			FMS LINING NUMBER(S)
			4729 (4")