






FRUEHAUF F-2 PARTS

PART NO.	NOTES	REPLACES
 SF1016	Spring Spacer Length 6-1/2" Width 3" Thickness 1-1/2"	Automann M 8144 BWP Dayton 338-1109 Euclid E-2838 Flagg FR276 Fruehauf UXA-000048 Meritor R302838
 SF1017	Spring Chair	Automann M 8142 BWP Dayton 338-1111 Euclid E-2837 Flagg FR204 Fruehauf AXA-000512-001 Meritor R302837
 SH1023	Delrin Spring Liner Length 8" Width 2-7/8" Thickness .043"	Automann DL 376 BWP M-2872 Dayton GL-294 Euclid E-2842 Flagg DL294/DL295 Fruehauf UCD-006632-002 Meritor R302842
 SF1018	Axle Bracket	Automann M 8140 BWP Dayton 338-1113 Euclid E-2836 Flagg FR203/I Fruehauf UXA-000495-001 Meritor R302836
 SF1020	Front Standard Under Mount Hanger	Automann M 6120 BWP Dayton 338-1100 Euclid E-2826 Flagg FR246/I Fruehauf UCF-002467-001 Meritor R302826
 SF1021	Center Standard Under Mount Hanger	Automann M 6122 BWP Dayton 338-1101 Euclid E-2827 Flagg FR273/I Fruehauf UXA-000034 Meritor R302827

Copyright 2005 Sirco Industries, Inc.