




# HUTCHENS REPLACEMENT PARTS

PART NO.	NOTES	REPLACES
<b>5R783123</b>	Grade 5 U-Bolt Assembly Thread $7/8'' - 14$ A = 12" B = 3" C = 3"	Automann BWP M-1499 Dayton 361-248 Euclid E-UB5161-12 Flagg UBK1245 Hutchens 7040-06/10 Meritor R30U5161-12
	Grade 5 U-Bolt Assembly Thread $7/8'' - 14$ A = 13" B = 3" C = 6"	Automann BWP Dayton 361-577 Euclid E-UB5161-13 Flagg Hutchens 7040-11/12 Meritor R30U5161-13
<b>5R783136</b>	Grade 5 U-Bolt Assembly Thread $7/8'' - 14$ A = 14" B = 3" C = 6"	Automann BWP M-1492 Dayton 361-218 Euclid E-UB5161-14 Flagg UBK1225 Hutchens 7040-13/14 Meritor R30U5161-14
<b>5R783146</b>	Grade 5 U-Bolt Assembly Thread $7/8'' - 14$ A = 18" B = 3" C = 6"	Automann BWP M-1493 Dayton 361-250 Euclid E-UB5161-18 Flagg UBK1335 Hutchens 7040-15/21 Meritor R30U5161-18
	Grade 5 U-Bolt Assembly Thread $7/8'' - 14$ A = 14" B = 5" C = 6"	Automann BWP M-1494 Dayton 361-252 Euclid E-UB5165-14 Flagg UBK1295 Hutchens 7816-05/14 Meritor R30U5165-14
<b>5R783186</b>	Grade 5 U-Bolt Assembly Thread $7/8'' - 14$ A = 18" B = 5" C = 6"	Automann BWP M-2798 Dayton 361-587 Euclid E-UB5165-18 Flagg UBK2695 Hutchens 7816-13/18 Meritor R30U5165-18
	Grade 5 U-Bolt Assembly Thread $7/8'' - 14$ A = 18" B = 5" C = 6"	Automann BWP M-2798 Dayton 361-587 Euclid E-UB5165-18 Flagg UBK2695 Hutchens 7816-13/18 Meritor R30U5165-18
<b>5R785186</b>		