



BRAKE REPAIR KITS

BENDIX 16-1/2" TRUCK AND TRACTOR BRAKE																									
	FR-1		REPLACES																						
	2 - B136 2 - B137 2 - B141 1 - B142 2 - B143 2 - B144 2 - B423	Roller Pin Roller Anchor Pin Spring Spring Bushing Pin	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 50%;"></th> <th style="width: 50%; text-align: center;">FR-1</th> <th style="width: 50%;"></th> <th style="width: 50%; text-align: center;">FR-1A</th> </tr> </thead> <tbody> <tr> <td>Batco</td> <td style="text-align: center;">08-114200</td> <td rowspan="8" style="vertical-align: middle; text-align: center;">K-300</td> <td style="text-align: center;">08-114212</td> </tr> <tr> <td>Bendix</td> <td style="text-align: center;">104628</td> </tr> <tr> <td>BWP</td> <td style="text-align: center;">M-K95</td> </tr> <tr> <td>Euclid</td> <td style="text-align: center;">E-7237</td> </tr> <tr> <td>Leland</td> <td style="text-align: center;">K-299</td> </tr> <tr> <td>Meritor</td> <td style="text-align: center;">R507081</td> </tr> <tr> <td>Midland</td> <td style="text-align: center;">CQ65520</td> </tr> <tr> <td>Spicer</td> <td style="text-align: center;">HK71</td> </tr> </tbody> </table>		FR-1		FR-1A	Batco	08-114200	K-300	08-114212	Bendix	104628	BWP	M-K95	Euclid	E-7237	Leland	K-299	Meritor	R507081	Midland	CQ65520	Spicer	HK71
		FR-1		FR-1A																					
Batco	08-114200	K-300	08-114212																						
Bendix	104628																								
BWP	M-K95																								
Euclid	E-7237																								
Leland	K-299																								
Meritor	R507081																								
Midland	CQ65520																								
Spicer	HK71																								
FR-1A		FMS LINING NUMBER(S)																							
Above Less: 2 - B141 Anchor Pin 2 - B144 Bushing		4515E (7")																							

BENDIX 16-1/2" TRUCK AND TRACTOR BRAKE - SPRINGS ONLY																			
	FR-1S		REPLACES																
	2 - B142 4 - B143	Spring Spring	<table border="1" style="width: 100%; border-collapse: collapse;"> <tbody> <tr> <td>Batco</td> <td style="text-align: center;">104624</td> </tr> <tr> <td>Bendix</td> <td style="text-align: center;">104624</td> </tr> <tr> <td>BWP</td> <td style="text-align: center;">E-7238</td> </tr> <tr> <td>Euclid</td> <td style="text-align: center;">E-7238</td> </tr> <tr> <td>Leland</td> <td style="text-align: center;">E-7238</td> </tr> <tr> <td>Meritor</td> <td style="text-align: center;">R507082</td> </tr> <tr> <td>Midland</td> <td style="text-align: center;">R507082</td> </tr> <tr> <td>Spicer</td> <td style="text-align: center;">R507082</td> </tr> </tbody> </table>	Batco	104624	Bendix	104624	BWP	E-7238	Euclid	E-7238	Leland	E-7238	Meritor	R507082	Midland	R507082	Spicer	R507082
	Batco	104624																	
Bendix	104624																		
BWP	E-7238																		
Euclid	E-7238																		
Leland	E-7238																		
Meritor	R507082																		
Midland	R507082																		
Spicer	R507082																		
FR-1S		FMS LINING NUMBER(S)																	
		4515E (7")																	

