




BRAKE REPAIR KITS

EATON 16-1/2" SINGLE ANCHOR PIN BRAKE - FORD			
	EK-3		REPLACES
	2 - B152 2 - B769 2 - B942 1 - B983	Roller Pin Spring Roller Spring	
For High Mount Shoes With Offset Retainer Pin		FMS LINING NUMBER(S)	
		4223A (5") 4317G (6") 4311J (7")	

EATON 16-1/2" "ES-II" "EXTENDED SERVICE" FRONT AXLE BRAKE			
	EF-2		REPLACES
	2 - B430K 2 - B431 2 - B433 2 - B434	Roller Retainer Spring Spring	
Use With "ES-II" Shoe And "ES" Cams Only		FMS LINING NUMBER(S)	
		4719 (5") 4725 (6")	

EATON 16-1/2" "ES" "EXTENDED SERVICE" BRAKE					
	ES-1		REPLACES		
	2 - B430K 2 - B431 1 - B432A 2 - B769	Roller Retainer Spring Spring			
	K-3		FMS LINING NUMBER(S)		
Use Only With "ES" Camshafts		FMS LINING NUMBER(S)			
		4709 (7")			

Copyright 2005 Sirco Industries, Inc.