



BRAKE REPAIR KITS

EATON 16-1/2" "ES-II" "EXTENDED SERVICE" BRAKE				
	ES-2		REPLACES	
			ES-2	K-4
	2 - B430K Roller 2 - B431 Retainer 1 - B432A Spring 2 - B434* Spring *Installed Coil End At Top	Batco 08-114900 BWP M-K105 Eaton 314147 Euclid E-10244/S E-4709ES2 Leland K-375 Meritor R507064 MKT4709ES2 Midland C65477/CQ65477 Spicer HK61/SD/XLS	08-114950 E-11319 CQ65416	
K-4		FMS LINING NUMBER(S)		
Spring Kit 1 - B432A Spring 2 - B434 Spring Use With "ES-II" Shoe And "ES" Cams Only		4719 (5") 4725 (6") 4709 (7") 4726 (8-5/8")		

EATON 16-1/2" "ES" AND "ES-II" DRIVE, STEER AND TRAILER AXLES				
	ES-12		REPLACES	
	2 - B430K Roller 2 - B431 Retainer 1 - B432A Spring 2 - B434 Spring 2 - B769 Spring Contains Both "ES" And "ES-II" Style Retainer Spring Use B434 Only On "ES-II" Shoes	Batco BWP Eaton Euclid Leland Meritor Midland Spicer	K-495	
FMS LINING NUMBER(S)		4709 (7")		

