


# BRAKE CAMSHAFTS - DRIVE AXLE

Meritor



LH	RH	A	B	C	NOTES	REPLACES	
<b>C148L</b>					"P" & "Q"	Batco 04-451152 BWP M-743L Euclid E-1148B Leland L-508	Meritor 2210D5360 Midland CS41016 Spicer 18-811
		11-1/2"	-	-		REPLACED BY C148CL	
	<b>C147R</b>				Camshaft Kit <b>B8646</b>	Batco 04-451151 BWP M-743R Euclid E-1147B Leland L-507	Meritor 2210C5359 Midland CS41017 Spicer 18-810
<b>C148CL</b>					"Q-Plus"	Batco BWP Euclid E-1148C Leland	Meritor Midland Spicer
		11-1/2"	-	-		REPLACED BY C147CR	
	<b>C147CR</b>				Camshaft Kit <b>B8707</b>	Batco BWP Euclid E-1147C Leland	Meritor Midland Spicer
<b>C703L</b>					"P" & "Q"	Batco 04-451172 BWP M-3181L Euclid E-4703A Leland L-2453	Meritor 2210Z5720 Midland CS41036 Spicer 18-787
		11-3/4"	-	-		REPLACED BY C703BL	
	<b>C702R</b>				Camshaft Kit <b>B8646</b>	Batco 04-451171 BWP M-3181R Euclid E-4702A Leland L-2452	Meritor 2210Y5719 Midland CS41037 Spicer 18-786
<b>C703BL</b>					"Q-Plus"	Batco BWP Euclid E-4703B Leland	Meritor Midland Spicer
		11-3/4"	-	-		REPLACED BY C702BR	
	<b>C702BR</b>				Camshaft Kit <b>B8707</b>	Batco BWP Euclid E-4702B Leland	Meritor Midland Spicer
<b>C709L</b>					"P" & "Q"	Batco BWP M-998L Euclid E-4709A Leland L-2451	Meritor Midland Spicer 18-813
		12-1/2"	-	-		REPLACED BY C709BL	
	<b>C708R</b>				Camshaft Kit <b>B8646</b>	Batco BWP M-998R Euclid E-4708A Leland L-2450	Meritor Midland Spicer 18-812
<b>C709BL</b>					"Q-Plus"	Batco BWP Euclid E-4709B Leland	Meritor Midland Spicer
		12-1/2"	-	-		REPLACED BY C708BR	
	<b>C708BR</b>				Camshaft Kit <b>B8707</b>	Batco BWP Euclid E-4708B Leland	Meritor Midland Spicer

Copyright 2005 Sirco Industries, Inc.