




BRAKE REPAIR KITS

MERITOR 14-1/2" "W" SERIES COACH BRAKE - STEER AXLE			
	BK-145F	REPLACES	
	<ul style="list-style-type: none"> 2 - BP-100 Spring 1 - BP-101 Lock 1 - BP-102 Lock Screw 1 - BP-103 Washer 2 - BP-104 Anchor Pin 2 - BP-105 Roller 2 - BP-112 Fitting 	<ul style="list-style-type: none"> Batco 08-125100 BWP Euclid E-10841 Leland Meritor KIT 6004 Midland Spicer HK87 	<p style="text-align: center;">FMS LINING NUMBER(S)</p> <p style="text-align: center;">4227G (4") 4398B (5") 4228B (6")</p>

MERITOR 14-1/2" "W" SERIES COACH BRAKE - STEER AXLE			
	BK-145FM	REPLACES	
	<ul style="list-style-type: none"> 2 - BP-100 Spring 2 - BP-102 Lock Screw 2 - BP-103 Washer 2 - BP-105 Roller 	<ul style="list-style-type: none"> Batco 08-125102 BWP Dexter Euclid E-10866 Leland Meritor Midland Spicer HK86 	<p style="text-align: center;">FMS LINING NUMBER(S)</p> <p style="text-align: center;">4227G (4") 4398B (5") 4228B (6")</p>

MERITOR 14-1/2" "W" SERIES COACH BRAKE - DRIVE AXLE			
	BK-145R	REPLACES	
	<ul style="list-style-type: none"> 1 - BP-106 Spring 4 - BP-107 Lock 2 - BP-108 Bushing 2 - BP-109 Roller 2 - BP-110 Anchor Pin 2 - BP-111 Lock 	<ul style="list-style-type: none"> Batco 08-125300 BWP Euclid E-10870 Leland Meritor KIT 6003 Midland Spicer HK84 	<p style="text-align: center;">FMS LINING NUMBER(S)</p> <p style="text-align: center;">4592A (10")</p>

Copyright 2005 Sirco Industries, Inc.