




RIM CLAMPS

TYPE	PART NO.	STUD	A	B	C	REPLACES
Gunite 	722	3/4"	1/2"	2-1/2"	3-5/8"	Batco 13-5014 BWP M-2460 Euclid E-5902 GLP GL-3243 Gunite WP722 Leland W-256 Meritor R005902G Spicer 52-1430
	725	3/4"	5/8"	2-1/2"	3-5/8"	Batco 13-5015 BWP M-2461 Euclid E-9023 GLP GL-3244 Gunite WP725 Leland W-418 Meritor R009023G
Gunite 	544	3/4"	1/2"	2"	2-1/8"	Batco 13-5009 BWP M-1173 Euclid E-5890 GLP GL-3246 Gunite WP544 Leland W-416 Meritor R005890 Spicer 52-1422
	515	3/4"	1/2"	2"	2-5/32"	Batco 13-5008 BWP M-1188 Euclid E-5889 GLP GL-3245 Gunite WP515 Leland W-415 Meritor R005889 Spicer 52-1421
	545	3/4"	3/4"	2"	2-5/32"	Batco 13-5010 BWP M-1189 Euclid E-5891 GLP GL-3247 Gunite WP545 Leland W-417 Meritor R005891 Spicer 52-1423
Gunite 	110	3/4"	1-3/16"	2-7/8"	2-3/8"	Batco 13-4530 BWP M-1243 Euclid E-5905A GLP GL-3256 Gunite W1110 Leland W-258 Meritor R005905AG Spicer 52-1336

Copyright 2005 Sirco Industries, Inc.