







AXLE NUTS

| PART NO. | NOTES | A.F. | THRD | THK | REPLACES |
|--|------------------------------------|-------------|-------------|------------|--|
|  2296 | Outer Nut | 2-1/4" | 1-1/2" - 12 | 7/16" | Batco BWP Euclid Leland Meritor 06-354 M-1956 E-2296 L-1331 R002296 1227B106 |
| | Use Wrench 1920 | | | | |
| | FD 900/1, FE 900 And FF 901/931 | | | | |
|  2299 | Inner Nut | 2-5/8" | 1-1/2" - 12 | 3/8" | Batco BWP Euclid Leland Meritor 06-358 M-1959 E-2299 L-1334 R002299 1227U541 |
| | Use Wrench 1922 | | | | |
| | FD 900/1, FE 900 And FF 901/931 | | | | |
|  2297 | Lock Washer | O.D. | I.D. | THK | Batco BWP Euclid Leland Meritor 06-355 M-1958 E-2297 L-1333 R002297 1229G475 |
| | | 2-3/4" | 1-17/32" | .187" | |
| | FD 900/1, FE 900 And FF 901/931 | | | | |
|  2298 | Lock | 3" | 1-1/2" | .048" | Batco BWP Euclid Leland Meritor 06-357 M-1957 E-2298 L-1332 R002298 1229F474 |
| | | | | | |
| | FD 900/1, FE 900 And FF 901/931 | | | | |
|  3568 | Inner Nut | 2-5/8" | 1-1/2" - 18 | 3/8" | Batco BWP Eaton Euclid Leland Meritor 815622 L-3568 |
| | Use Wrench 1922 | | | | |
| | Eaton/Dana 10,12,13, 14,000# | | | | |
|  3569 | Outer Nut | 2-1/4" | 1-1/2" - 18 | 7/16" | Batco BWP Eaton Euclid Leland Meritor 815638 L-3569 |
| | Use Wrench 1920 | | | | |
| | Eaton/Dana 10,12,13, 14,000# | | | | |

Copyright 2005 Sirco Industries, Inc.