



BRAKE REPAIR KITS


MERITOR 15" "Q" FRONT BRAKE

	RF-3		REPLACES		
			RF-3		RF-3A
	2 - 073	Lock Nut	Batco	08-111100	08-111102
2 - B725	Roller	BWP	M-K79	M-K79B	
2 - B950	Anchor Pin	Euclid	E-3869	E-7899	
1 - B951	Wear Plate		E-1308Q	E-1308QMA	
1 - B952	Spring	Leland	K-283	K-282	
1 - B953	Spring	Meritor	KIT 8029	KIT 8061	
2 - B954	Washer		MKT1308Q		
2 - B955	Clip	Midland	CQ69001	C67899 CQ67899	
		Spicer	HK55	HK77	
	RF-3A		FMS LINING NUMBER(S)		
2 - B725	Roller	1308T (4")			
1 - B952	Spring				
1 - B953	Spring				

MERITOR 15" "Q-PLUS" FRONT AND DRIVE AXLE BRAKES

	RF-5		REPLACES		
			FMS LINING NUMBER(S)		
	2 - B120	Anchor Pin	Batco	08-116000/04	
2 - B161	Retainer	BWP	M-K98		
2 - B220	Spring	Euclid	E-9064		
2 - B423	Pin		E-4702		
2 - B888S	Bushing	Leland	K-318		
2 - B911	Roller		K-318K		
1 - B956	Spring	Meritor	KIT 8824HD MKT4702KTK		
		Midland	C65642 CQ65642		
		Spicer	HK66XLS		
		FMS LINING NUMBER(S)			
		4702 (4") 4703 (5")			
		4704 (6") 4705 (7")			

MERITOR 15" "T" SERIES HOLD DOWN KIT

	ARK		REPLACES		
	Parts Not Sold Separately		FMS LINING NUMBER(S)		
			Batco	01-390	
		BWP	M-2720		
		Euclid	E-4800		
		Leland	K-259(2)		
		Meritor	KIT 9425		
		Midland	CQ66759		
		Spicer	19-921		
		FMS LINING NUMBER(S)			
		1307 (3-1/2")			
		1308 (4")			

Copyright 2005 Sirco Industries, Inc.