







# HUTCHENS REPLACEMENT PARTS

PART NO.	NOTES	REPLACES	
 <b>SH1009</b>	Equalizer Step Bolt  For H-2200/H-7600/H-7700/CH-7600 And CH-7700  Diameter                    3/4" Length                        6" Thread                         5/8" - 18	Automann    TRS 4413 BWP            M-1453 Dayton        334-366 Euclid         E-2000 Flagg          H110 Hutchens     7016-01 Meritor        R302000	
 <b>SH1010</b>	Tab Lock	Automann    MH 456 BWP            M-1454 Dayton        334-360 Euclid         E-2001 Flagg          H105 Hutchens     729-00 Meritor        R302001	
 <b>SH1011</b>	Nut  Thread                        5/8" - 18 Hex                              15/16" Height                         17/32"	Automann    PNF 106 BWP            M-1455 Dayton        SLN-104 Euclid         E-2002 Flagg          LN104 Hutchens     37-03 Meritor        R302002	
 <b>SH1045</b>	Rebound Bolt  Thread                        5/8" - 18 Length                        4-1/2"	Automann    F 580412 GR5 BWP Dayton Euclid         E-3415 Flagg          B1324-43* Hutchens     759-00 Meritor        R303415	
 <b>SH1046</b>	Spacer Sleeve  Outside Diameter            7/8" Inside Diameter              21/32" Length                         3-7/32"	Automann    MH 558 BWP Dayton        334-361 Euclid         E-3416 Flagg          H156 Hutchens     756-00 Meritor        R303416	
 <b>SH1048</b>	Fabricated Equalizer  For H-9700  Includes SH1049 Bushing	Automann    EQ 019 BWP            M-3482 Dayton        338-886 Euclid         E-7532 Flagg          H220/I Hutchens     16158-01 Meritor        R307532	

Copyright 2005 Sirco Industries, Inc.