



REYCO 21B PARTS

PART NO.	NOTES	REPLACES														
 SR1000	Equalizer - Trailer Model 21B Bushings Not Included Uses SR1001 Bushing Assembly	<table border="0"> <tr><td>Automann</td><td>EQ 001</td></tr> <tr><td>BWP</td><td>M-1670</td></tr> <tr><td>Dayton</td><td>338-199</td></tr> <tr><td>Euclid</td><td>E-2846A</td></tr> <tr><td>Flagg</td><td>R103</td></tr> <tr><td>Meritor</td><td>R302846A</td></tr> <tr><td>Reyco</td><td>T-5427</td></tr> </table>	Automann	EQ 001	BWP	M-1670	Dayton	338-199	Euclid	E-2846A	Flagg	R103	Meritor	R302846A	Reyco	T-5427
Automann	EQ 001															
BWP	M-1670															
Dayton	338-199															
Euclid	E-2846A															
Flagg	R103															
Meritor	R302846A															
Reyco	T-5427															
 SR1001/SR1001U	Equalizer Bushing Assembly Model 21B Includes: (2) SR1002 Bushing (1) SR1003 Shaft (2) SR1004 Washer (2) SR1005 Washer (2) SR1006 Bolt SR1001U Contains SR1002U Bushing	<table border="0"> <tr><td>Automann</td><td>TRK 5066</td></tr> <tr><td>BWP</td><td>M-2936</td></tr> <tr><td>Dayton</td><td>334-211</td></tr> <tr><td>Euclid</td><td>E-3976/E-9555</td></tr> <tr><td>Flagg</td><td>R233</td></tr> <tr><td>Meritor</td><td>R303976/R309555</td></tr> <tr><td>Reyco</td><td>TK-12506 TK-18998</td></tr> </table>	Automann	TRK 5066	BWP	M-2936	Dayton	334-211	Euclid	E-3976/E-9555	Flagg	R233	Meritor	R303976/R309555	Reyco	TK-12506 TK-18998
Automann	TRK 5066															
BWP	M-2936															
Dayton	334-211															
Euclid	E-3976/E-9555															
Flagg	R233															
Meritor	R303976/R309555															
Reyco	TK-12506 TK-18998															
 SR1002/SR1002U	Equalizer Bushing Model 21B SR1002U Is Polyurethane Outside Diameter 3-3/8" Inside Diameter 1-5/8" Length 4-13/32"	<table border="0"> <tr><td>Automann</td><td>TRB 5066/UB</td></tr> <tr><td>BWP</td><td>M-1719</td></tr> <tr><td>Dayton</td><td>321-146/U</td></tr> <tr><td>Euclid</td><td>E-1159/E-8653</td></tr> <tr><td>Flagg</td><td>R110/UB</td></tr> <tr><td>Meritor</td><td>R301159/R308653</td></tr> <tr><td>Reyco</td><td>T-5524</td></tr> </table>	Automann	TRB 5066/UB	BWP	M-1719	Dayton	321-146/U	Euclid	E-1159/E-8653	Flagg	R110/UB	Meritor	R301159/R308653	Reyco	T-5524
Automann	TRB 5066/UB															
BWP	M-1719															
Dayton	321-146/U															
Euclid	E-1159/E-8653															
Flagg	R110/UB															
Meritor	R301159/R308653															
Reyco	T-5524															
 SR1003	Equalizer Shaft Model 21B Outside Diameter 1-5/8" Length 8-11/16" Bolt Holes 1" - 8	<table border="0"> <tr><td>Automann</td><td>TRS 4003</td></tr> <tr><td>BWP</td><td>M-3432</td></tr> <tr><td>Dayton</td><td>334-207</td></tr> <tr><td>Euclid</td><td>E-3972</td></tr> <tr><td>Flagg</td><td>R104</td></tr> <tr><td>Meritor</td><td>R303972</td></tr> <tr><td>Reyco</td><td>14247-01</td></tr> </table>	Automann	TRS 4003	BWP	M-3432	Dayton	334-207	Euclid	E-3972	Flagg	R104	Meritor	R303972	Reyco	14247-01
Automann	TRS 4003															
BWP	M-3432															
Dayton	334-207															
Euclid	E-3972															
Flagg	R104															
Meritor	R303972															
Reyco	14247-01															
 SR1004	Equalizer Washer Model 21B Outside Diameter 3-3/4" Inside Diameter 1-1/16" Thickness 1/2"	<table border="0"> <tr><td>Automann</td><td>WA 06</td></tr> <tr><td>BWP</td><td>M-2811</td></tr> <tr><td>Dayton</td><td>334-208</td></tr> <tr><td>Euclid</td><td>E-1986A</td></tr> <tr><td>Flagg</td><td>R109</td></tr> <tr><td>Meritor</td><td>R301986A</td></tr> <tr><td>Reyco</td><td>14249-01</td></tr> </table>	Automann	WA 06	BWP	M-2811	Dayton	334-208	Euclid	E-1986A	Flagg	R109	Meritor	R301986A	Reyco	14249-01
Automann	WA 06															
BWP	M-2811															
Dayton	334-208															
Euclid	E-1986A															
Flagg	R109															
Meritor	R301986A															
Reyco	14249-01															
 SR1005	Equalizer Shaft Lock Washer Model 21B Inside Diameter 1" Thickness 3/8"	<table border="0"> <tr><td>Automann</td><td>LW 109</td></tr> <tr><td>BWP</td><td>M-3434</td></tr> <tr><td>Dayton</td><td>SLW-34</td></tr> <tr><td>Euclid</td><td>E-3975</td></tr> <tr><td>Flagg</td><td>HLW107</td></tr> <tr><td>Meritor</td><td>R303975</td></tr> <tr><td>Reyco</td><td>14250-01</td></tr> </table>	Automann	LW 109	BWP	M-3434	Dayton	SLW-34	Euclid	E-3975	Flagg	HLW107	Meritor	R303975	Reyco	14250-01
Automann	LW 109															
BWP	M-3434															
Dayton	SLW-34															
Euclid	E-3975															
Flagg	HLW107															
Meritor	R303975															
Reyco	14250-01															

Copyright 2005 Sirco Industries, Inc.