





REYCO 21B PARTS

PART NO.	NOTES	REPLACES
 SH1023	Delrin Spring Liner Length 8" Width 2-7/8" Thickness .043"	Automann DL 376 BWP M-2872 Dayton GL-294 Euclid E-2842 Flagg DL294/DL295 Meritor R302842 Reyco T-5166
 SH1016	U-Bolt Washer Heat Treated Outside Diameter 1-3/4" Inside Diameter 15/16" Thickness 1/8"	Automann MUBW 184 BWP M-2136 Dayton 334-150 Euclid E-2546 Flagg UBW80 Meritor R302546 Reyco T-7292
 SH1039	U-Bolt Hi-Nut Grade 8 Thread 7/8" - 14 Across Flats 1-1/4" Height 1-5/32"	Automann DN 5 BWP M-1194 Dayton DN-78 Euclid E-3002A Flagg DN5 Meritor R303002A Reyco 09352-01
5R783146	Grade 5 U-Bolt Assembly Thread 7/8" - 14 A = 14" B = 3" C = 6"	Automann M-1492 BWP 361-218 Dayton E-UB5161-14 Euclid UBK1225 Flagg R30U5161-14 Meritor 08490/08495-01 Reyco
 5R783186	Grade 5 U-Bolt Assembly Thread 7/8" - 14 A = 18" B = 3" C = 6"	Automann M-1493 BWP 361-250 Dayton E-UB5161-18 Euclid UBK1335 Flagg R30U5161-18 Meritor 08495/08504-01 Reyco