

INTERCHANGES

FRUEHAUF	OUR #	FRUEHAUF	OUR #	GLP	OUR #
305680-900	B8650	UXA-0011-900	SF1009	GL-1001	708AR
ACA3265/6	B8635	UXA-00015-001	SF1003	GL-1002	709AL
ACC001996-902	FK-1HD	UXA-000016	SF1010	GL-1003	896R
ACC6113-900	9016	UXA-000017	SF1000	GL-1004	896L
ACC7538-900	9013	UXA-000026-001	SF1008	GL-1005	897R
ACD2233-1	B868	UXA-000034	SF1021	GL-1006	897L
ACD2285-900	B8624	UXA-000048	SF1016	GL-1009	306R
ACD2287-1	B869	UXA-000356-001	SF1013	GL-1010	306L
ACE8510-001	5401	UXA-000356-002	SF1006	GL-1011	988R
ACE9909-001	B377	UXA-000495-001	SF1018	GL-1012	988L
ACE009911	B302	ZCF003435901	CMBK	GL-2001	891AR
ACF1328-001	B498			GL-2002	892AL
ACF3378-001	B277			GL-2003	891BR
ACF4021-1	B8727			GL-2004	892BL
ACF4022-1	B8727			GL-2009	304R
ACF4024-1	B8728			GL-2010	304L
ACF4024-900	B8725A			GL-2013	912R
AXA0068	B495S			GL-2014	913L
AXA0408-1	5402			GL-2021	996R
AXA0413-900	B8620			GL-2022	996L
AXA0417-1	B8619			GL-2101	888RZ
AXA0418-1	B8622			GL-2102	889LZ
AXA0420-1	C563L			GL-2103	995R
AXA0420-2	C564R			GL-2104	995L
AXA0420-3	C101L			GL-2301	333B
AXA0420-4	C100R			GL-2302	881M
AXA0420-5	C862R			GL-3001	654
AXA0420-6	C861L			GL-3003	715
AXA0420-900	B8649			GL-3004	149
AXA0429-900	B8623			GL-3005	716
AXA0430-1	B8734			GL-3006	716S
AXA-000512-001	SF1017			GL-3083	399
FSP 005-05 KIT	LGBK			GL-3085	853
FSP-00602PK9	SR1011			GL-3087	729
MBCBK0013	FK-1			GL-3096	123
MBCBK0014	FK-2HD			GL-3097	235
UCC-005998-001	SF1015			GL-3098	993
UCD-006632-002	SH1023			GL-3099	053
UCE-008801-001	SF1014			GL-3103	708
UCF-002467-001	SF1020			GL-3112	256
UCF-002470-001	SF1022			GL-3113	257
UCF-002640-001	SF1007			GL-3114	302
UCF-006963	SF1001			GL-3158	008
UXA-000002	SF1012			GL-3243	722
UXA-000003	SF1005			GL-3244	725
UXA-000004	SF1004			GL-3245	515
UXA-0004-900	SF1002			GL-3246	544
UXA-000011	SF1011			GL-3247	545

Copyright 2005 Sirco Industries, Inc.