


## NEW LINED SHOES/LINED SHOE KITS



APPLICATION	FMS NO.	RATING	PART NO.	SHOES	KIT
Eaton 15 x 4	1308TT	23K	L1308E L1308E-EF1	(2) L1308E	(1) EF-1
Eaton 15 x 4 "ES"	1443TT	23K	L1443E L1443E-EF1	(2) L1443E	(1) EF-1
Meritor 15 x 4 "Q"	1308TT	23K	L1308Q L1308Q-RF3	(2) L1308Q	(1) RF-3
Meritor 15 x 4 "Q-Plus"	4702	23K	L4702Q L4702Q-RF5	(2) L4702Q	(1) RF-5
Eaton 16-1/2 x 7	4311J	23K	L4311J L4311J-EK1HD	(2) L4311J	(1) EK-1HD
Eaton 16-1/2 x 7 "ES-II"	4709	23K	L4709N L4709N-ES2	(2) L4709N	(1) ES-2
Fruehauf 16-1/2 x 7	4515E	23K	L4515X L4515X-XK3HD	(2) L4515X	(1) XK-3HD
Mack 16-1/2 x 5 "Q"	4524B	20K	L4524M L4524M-MF2	(2) L4524M	(1) MF-2
Meritor 16-1/2 x 5 "Q"	4524B	20K	L4524Q L4524Q-QK1HD	(2) L4524Q	(1) QK-1HD
Meritor 16-1/2 x 7 "Q"	4515E	20K	L4515Q-20 L4515Q-20-QK1 L4515Q-20-QK1HD	(2) L4515Q-20 (2) L4515Q-20	(1) QK-1 (1) QK-1HD
Meritor 16-1/2 x 7 "Q"	4515E	23K	L4515Q L4515Q-QK1HD	(2) L4515Q	(1) QK-1HD
Meritor 16-1/2 x 7 "Q-Plus"	4707	20K	L4707Q-20 L4707Q-20-QK1 L4707Q-20-QK1HD	(2) L4707Q-20 (2) L4707Q-20	(1) QK-1 (1) QK-1HD
Meritor 16-1/2 x 7 "Q-Plus"	4707	23K	L4707 L4707-QK1HD	(2) L4707	(1) QK-1HD

Copyright 2005 Sirco Industries, Inc.