


# BRAKE CAMSHAFTS - TRAILER

Meritor 4000 - 6000



LH	RH	A	B	C	NOTES	REPLACES	
C447L		REPLACED BY C447AL			10 - Spline "Q"	Batco 04-881732	Meritor 2210S4179
		17-5/16"	2-5/64"	1-25/32"		Double-Grooved	BWP M-993L Euclid E-2447 Leland L-1652
C448R		REPLACED BY C448AR			Camshaft Kits B8683 B8747	Batco 04-881731	Meritor 2210R4178
						Double-Grooved	BWP M-993R Euclid E-2448 Leland L-1651
C447AL		17-5/16"	2-5/64"	1-25/32"	10 - Spline "Q-Plus"	Batco	Meritor R607066
						Double-Grooved	BWP Euclid E-2447A Leland
C448AR		REPLACED BY C448AL			Camshaft Kits B8683 B8747	Batco	Meritor R607065
						Double-Grooved	BWP Euclid E-2448A Leland
C441L		REPLACED BY C441BL			28 - Spline "Q"	Batco 04-891732	Meritor 2210M4329
		17-5/16"	2-5/64"	1-25/32"		Double-Grooved	BWP M-990L Euclid E-2441A Leland L-1299
C442R		REPLACED BY C442BR			Camshaft Kits B8683 B8747	Batco 04-891731	Meritor 2210L4328
						Double-Grooved	BWP M-990R Euclid E-2442A Leland L-1298
C441BL		17-5/16"	2-5/64"	1-25/32"	28 - Spline "Q-Plus"	Batco 04-931732	Meritor 2210C6867
						Double-Grooved	BWP M-3170L Euclid E-2441B/E-5506 Leland L-3113
C442BR		REPLACED BY C442BL			Camshaft Kits B8683 B8747	Batco 04-931731	Meritor 2210B6866
						Double-Grooved	BWP M-3170R Euclid E-2442B/E-5507 Leland L-3112
C449L		REPLACED BY C449AL			10 - Spline "Q"	Batco 04-882042	Meritor 2210W4183
		20-13/32"	2-5/64"	1-25/32"		Double-Grooved	BWP M-994L Euclid E-2449 Leland L-1656
C450R		REPLACED BY C450AR			Camshaft Kits B8683 B8747	Batco 04-882041	Meritor 2210V4182
						Double-Grooved	BWP M-994R Euclid E-2450 Leland L-1655
C449AL		20-13/32"	2-5/64"	1-25/32"	10 - Spline "Q-Plus"	Batco	Meritor R607070
						Double-Grooved	BWP Euclid E-2449A Leland
C450AR		REPLACED BY C450AL			Camshaft Kits B8683 B8747	Batco	Meritor R607069
						Double-Grooved	BWP Euclid E-2450A Leland