



# BRAKE CAMSHAFTS - TRAILER

Spicer 12-1/4"

Double-Grooved



1 1/16"

LEFT HAND

"A" Dimension: under head to beginning of lock ring groove

1-1/2" Dia. - 10 Spline

LH	RH	A	B	C	NOTES	REPLACES			
C411L		21-1/8"	2-21/32"	2-7/32"	Std Forge 202103-213L/R	Batco	04-612122	Meritor	R607006
					BWP	M-477L	Midland	CS41762	
					Camshaft Kits	Euclid	E-1411	Spicer	17-685
						Leland	L-1075		M12WK107-6
	C410R				B8655	Batco	04-612121	Meritor	R607005
					B8655Z	BWP	M-477R	Midland	CS41763
						Euclid	E-1410	Spicer	17-684
						Leland	L-1074		M12WK106-6
C423L		23-1/4"	2-21/32"	2-7/32"	Std Forge 202103-233L/R	Batco	04-612322	Meritor	R607010
					BWP	M-478L	Midland	CS41718	
					Camshaft Kits	Euclid	E-1423	Spicer	17-691
						Leland	L-734		M12WK101-17
	C422R				B8655	Batco	04-612321	Meritor	R607009
					B8655Z	BWP	M-478R	Midland	CS41719
						Euclid	E-1422	Spicer	17-690
						Leland	L-733		M12WK100-17
C421L		23-7/8"	2-21/32"	2-7/32"	Std Forge 202103-241L/R	Batco	04-612402	Meritor	R607008
					BWP	M-479L	Midland	CS41722	
					Camshaft Kits	Euclid	E-1421	Spicer	17-695
						Leland	L-736		M12WK101-19
	C420R				B8655	Batco	04-612401	Meritor	R607007
					B8655Z	BWP	M-479R	Midland	CS41723
						Euclid	E-1420	Spicer	17-694
						Leland	L-735		M12WK100-19